

Environment Report

Month - July 2023

| | |
|---------------------------|----------------------------------------------------------------------------|
| Name of the Plant: | Asian Fine Cements Private Limited |
| Address: | Village Rajgarh Near Shambu Barrier Rajpura, Patiala (Punjab) 140417 |

Monthly Average Data

| 1. Online Stack Monitoring (Particulate Matter) | Result | Regulatory Standard |
|-------------------------------------------------|-------------------------------|-------------------------------|
| Name of the Stack | PM (mg/Nm³) | PM (mg/Nm³) |
| HRP and Ball Mill | 15.8 | 30.0 |

2. Ambient Air Quality

| Name of the Location | PM ₁₀ (µg/m ³) (Limit-100) | PM _{2.5} (µg/m ³) (Limit-60) |
|----------------------------------------------|------------------------------------------------------|------------------------------------------------------|
| Station-I Near Main Gate (Security building) | 68.9 | 43.2 |
| Station-II Towards Poultry farm | 70.0 | 44.0 |
| Station-III Towards village Ramnagar | 69.4 | 41.4 |

3. Sewage Treatment Plant (STP) - Treated Water Characteristics

| Sr. No | Parameters | Unit | Result | Standard Value |
|--------|--------------|------|--------|----------------|
| 1 | pH | - | 7.1 | 5.5-9.0 |
| 2 | TSS | mg/l | 18.7 | 100.0 mg/l |
| 3 | TDS | mg/l | 1270 | 2100 mg/l |
| 4 | COD | mg/l | 38 | 250 mg/l |
| 5 | BOD | mg/l | 10.8 | 30 mg/l |
| 6 | Oil & Grease | mg/l | BDL | 10 mg/l |